

Rapport d'inspection – 2026 Case 1107 NX-D

Numéro de série: NKJ1107NETKT10858 | Heure: 4 | Lieu: Dubai, Émirats arabes unis | SKU: 858

Key Features & Condition

Safety Certification Label	N/A
Equipment Parts Manual	N/A
Horn Function	Yes
Travel Alarm	Yes
Operator's Manual	Yes
Emission Compliance Label	N/A
Emergency Switch	Yes
EPA	N/A
Closed cabin	N/A
Control Protection	Yes
Tools	N/A
Aircondition / Heater	N/A
Water Spray System	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Control Levers, Control Swithces	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Windows& mirrors	No window, 2 mirrors
Wiper, washer	N/A
Electrical System	Ok
Cabin Structure	Ok
Floor cover mat	N/A

Engine & Performance

Fuel Injection System Type	Electronic
Engine Model Details	H4C510122
Fluid Leaks	Ok



Engine Oil Check	Ok
Exhaust System and Muffler	Ok
Exhaust Smoke	Normal
Engine Cooling System	Ok
Engine Blow-by Check	Normal
Belts and Air/Oil Filters	Ok
Coolant	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Stairs, Handrails	Ok
Paintwork	Ok
Water tanks	N/A
Drum Condition	Ok
Rubber Drum Isolators	Ok
Drum Scraper	Ok
Lights	Ok, 1- light protection has little dent.
Batteries	Ok

Hydraulic System

Hoses & Lines	Ok
Drum Vibration Motors	Ok
Pumps & Valves	Ok
Steering Cylinders	Ok
Hydraulic Tank	Ok

Limited Functional Testing & Operation

Steering	Ok
Transmission Test	Ok
Dash Console	Ok
Brake/Park Brake	Ok
Water Spray System	N/A
Drive Motors Front	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Drive Motors RearOk

Drum VibrationOk

Tires Condition (%)	
Right	100%, CEAT, 23.1-26R3, New, Tubeless
Left	100%, CEAT, 23.1-26R3, New, Tubeless

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

