

Rapport d'inspection – 2006 Toyota 4JD25

Numéro de série: 99213 | Heure: 8965 | Lieu: United Arab Emirates | SKU: 724

Key Features & Condition

Safety Certification Label	N/A
Axle Based 4WD	Yes
Electric Powered	N/A
Equipment Parts Manual	N/A
Electric Operating System	Yes
Horn Function	Yes
Travel Alarm	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Upper Control Station	Yes
Extension Deck	Yes
Diesel Powered	Yes

Engine

Model	ISUZU CC-4JG1
Injection	Mechanical
Leaks	Ok
Oil Condition	Ok
Exhaust Smoke	Normal
Cooling System	Ok
Coolant	Ok
Sound	Ok
Blow By	Normal
Belts	Ok
Power	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Sheet Metal	Ok



Side Doors	Ok
Boom Linkage	Ok
Paintwork	Ok, repainted
Cooler Grill	Ok
Frame Condition	Ok
Platform Condition	Ok
Batteries	Ok

Hydraulic System

Hoses, Lines, Swivel	Ok
Pump And Valve Bloc	Ok
Steering Cylinder	Ok
Platform Angle Cylinder	N/A
Boom Cylinder	Ok
Jip Cylinder	N/A
Platform Rotation Cylinder	Ok

Limited Functional Testing & Operation

Drive Forward	Ok
Drive Reverse	Ok
Steering	Ok
Platform Function Controls	Ok
Boom Extension	Ok
360° Continuous Turret Rotation	Ok
Platform Angle	N/A
Wheel Bearing	Ok
Platform Control	Ok
Brake System	Ok
Lifting	Ok
Platform Rotation	Ok
Jib	N/A

Tires Condition / Type

Axle 1 Right	50% /solid
--------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Axle 1 Left	60% /solid
Axle 2 Right	50% /solid
Axle 2 Left	50% /solid

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

