

## Rapport d'inspection – 2013 Caterpillar M318D

Heure: 16335.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1402034

---

### Key Features & Condition

|                                   |     |
|-----------------------------------|-----|
| Safety Certification Label        | N/A |
| Boom Hydraulic Check Valve        | Yes |
| Adjustable Boom System            | N/A |
| Automatic Lubrication System      | N/A |
| Arm Hydraulic Check Valve         | Yes |
| Back camera                       | Yes |
| Quick Coupler                     | N/A |
| Hydraulic Hammer Lines            | Yes |
| Grapple and Shear Hydraulic Lines | N/A |
| Mono Boom                         | Yes |
| Stabilizer Blade Condition        | Yes |
| Horn                              | Yes |

### Operator Cabin Details

|                                   |                   |
|-----------------------------------|-------------------|
| Seat and Arm Support              | Ok                |
| Cab Doors & covers                | Ok                |
| Control Levers, Control Stick     | Ok                |
| Windows and Mirrors               | Ok                |
| Dashboard Screen, Gauges          | Ok                |
| Warning alarms message            | Ok                |
| Washer, Wipers                    | No control switch |
| Air Conditioning & Heating System | Ok                |
| Cab Floor Covering                | Ok                |
| Cab Structure, Gard               | Ok, no Gard       |
| Electrical System                 | Ok                |

### Engine & Performance

|                     |            |
|---------------------|------------|
| Fuel Injection Type | Electronic |
| Engine Model        | C6.6       |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                           |
|--------------------------|---------------------------|
| Engine Cooling System    | Ok                        |
| Engine Oil Check         | Ok, need change           |
| Blowby                   | Normal                    |
| Exhaust System & Muffler | Ok                        |
| Belts & Air/Oil Filters  | Ok                        |
| Smoke                    | Normal                    |
| Coolant                  | Ok                        |
| Leaks& seals             | Minor oil pan Gasket leak |

---

## Exterior Condition & Visual Inspection

|                             |                        |
|-----------------------------|------------------------|
| Main Frame & Track Frame    | Ok                     |
| Protective Covers & Sheets  | Ok                     |
| Engine Hood                 | Ok                     |
| Side Access Doors           | Ok                     |
| Steps and Handrails         | Ok                     |
| Boom Condition              | Ok                     |
| Bumpers & Catwalk Condition | Ok                     |
| Arm Condition               | Ok                     |
| Lights                      | Ok, 1 bulb need change |
| Battery Check               | Ok                     |
| Counterweight               | Ok                     |
| Exterior Paint Condition    | Ok                     |

---

## Hydraulic System

|                              |    |
|------------------------------|----|
| Hydraulic Leaks              | Ok |
| Boom Hydraulic Jack          | Ok |
| Hydraulic Pump & Valve Block | Ok |
| Mono Boom Jack               | Ok |
| Bucket Hydraulic Jack        | Ok |
| Arm Hydraulic Jack           | Ok |
| Pump Noises Check            | Ok |
| Bucket Swing cylinder        | Ok |

---

## Transmission & drive train

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                   |    |
|-------------------|----|
| Transmission Gear | Ok |
| Axles             | Ok |
| Swivel Joint      | Ok |
| Universal Joint   | Ok |

---

## Limited Functional Testing & Operation

|                                     |    |
|-------------------------------------|----|
| Boom Pins Condition                 | Ok |
| Excavator self- Drift Test          | Ok |
| Arm Pins Condition                  | Ok |
| Hydraulic Pump Noise Check          | Ok |
| Brack & Parking Brack               | Ok |
| Suspension Lock                     | Ok |
| Bucket Pins Condition               | Ok |
| Slewing Ring Bearing Movement Check | Ok |
| Swing Drive and Brake Test          | Ok |
| Drive force Test                    | Ok |
| Slewing Ring Lock                   | Ok |

---

## Attachments

|                          |                      |
|--------------------------|----------------------|
| Attachments model        | digging bucket       |
| Size                     | W820, H1100, D800 mm |
| Status                   | Ok                   |
| Coupler status           | Ok                   |
| Second Attachments model | N/A                  |
| Size                     | N/A                  |
| Status                   | N/A                  |

---

## Tires Estimated Remaining Life %

|             |             |
|-------------|-------------|
| Front Right | 70%         |
| Front Left  | 70%         |
| Rear Right  | 70%         |
| Rear Left   | 70%         |
| Size        | 10.00-20    |
| Type        | Twin / Mono |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Spacer Rings

No

Damages / Cuts

No

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

