

**Rapport d'inspection – 2017 Caterpillar D8R**

Heure: 21075.0 | Lieu: Dubai, Émirats arabes unis | SKU: 1413246

**Key Features & Condition**

|                            |     |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Ground Ripper              | Yes |
| Ripper Control Valve       | Yes |
| Low Ground Pressure Tracks | N/A |
| Operator's Manual          | N/A |
| Emission Compliance Label  | N/A |
| Grade Control System       | N/A |
| Equipment Parts Manual     | N/A |
| CAT System One             | N/A |
| Radio                      | Yes |
| Horn                       | Yes |

**Operator Cabin Details**

|                                   |               |
|-----------------------------------|---------------|
| Seat and Arm Support              | Ok            |
| Cab Doors & covers                | Ok            |
| Controls, Levers                  | Ok            |
| Windows and Mirrors               | Ok            |
| Dashboard Screen, Gauges          | Ok            |
| Warning alarms message            | Ok            |
| Washer, Wipers                    | Ok            |
| Air Conditioning & Heating System | Not cooling   |
| Cab Floor Covering                | Ok, has a cut |
| Cab Structure, Gard               | Ok            |
| Electrical System                 | Ok            |

**Engine & Performance**

|                       |            |
|-----------------------|------------|
| Fuel Injection Type   | Electronic |
| Engine Model          | C15        |
| Engine Cooling System | Ok         |

**PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

# PLANT & EQUIPMENT AUCTIONS

---

|                          |                  |
|--------------------------|------------------|
| Engine Oil Check         | Ok               |
| Blowby                   | Normal           |
| Exhaust System & Muffler | Ok               |
| Belts & Air/Oil Filters  | Ok               |
| Smoke                    | Normal           |
| Coolant                  | Ok, normal water |
| Fluid Leaks              | Ok               |

---

## Exterior Condition & Visual Inspection

|                                   |                                   |
|-----------------------------------|-----------------------------------|
| Push Frame & Trunnions            | Ok                                |
| Doors, Covers, and Grilles        | Ok                                |
| Access Steps & Handrails          | Ok                                |
| Exterior Paint Condition          | Ok                                |
| Blade Trunnions & Bushings        | Ok                                |
| Underbody Protection Plates       | Ok                                |
| Final Drive Condition             | Ok                                |
| Fuel Tank, Roof, & Hood Condition | Ok                                |
| Lights and Battery Check          | Ok, lights need wiring connecting |
| Push Arm Pivot Shaft              | Ok                                |
| Tilt Linkage Pins & Bushings      | Ok                                |

---

## Hydraulic System

|                              |     |
|------------------------------|-----|
| Hydraulic Leaks              | Ok  |
| Lift Hydraulic Jacks         | Ok  |
| Ripper Lift Hydraulic Jacks  | Ok  |
| Tilt Hydraulic Jack          | Ok  |
| Angle Hydraulic Jack         | N/A |
| Ripper Angle Hydraulic Jacks | Ok  |

---

## Limited Functional Testing & Operation

|                         |                 |
|-------------------------|-----------------|
| Push Frame Pins         | Ok, minor Loose |
| Blade Pins              | Ok, minor Loose |
| Ripper Pins             | Ok              |
| Equalizer Bar Condition | Ok              |

---

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                 |
|--------------------------|-----------------|
| Bulldozer Stall Test     | Ok              |
| Steering Function Test   | Ok              |
| Blade Tilt and Lift Test | Ok              |
| Undercarriage Pivot Pins | Ok, minor Loose |
| Transmission Test        | Ok              |
| Brake System Test        | Ok              |
| Torque Converter Test    | Ok              |
| Electric system check    | Ok              |

## Blade Inspection

|                       |    |
|-----------------------|----|
| Blade Base Condition  | Ok |
| Spill Rack Condition  | Ok |
| Blade Front Condition | Ok |
| Blade Edge Condition  | Ok |

## Undercarriage Inspection

|                                    |     |
|------------------------------------|-----|
| Right Side Undercarriage Condition | -   |
| Undercarriage Bushings             | 75% |
| Undercarriage Shoes                | 80% |
| Front Idler Condition              | 80% |
| Rear Idler Condition               | 70% |
| Carrier Roller Condition           | N/A |
| Track Links Condition              | 80% |
| Sprocket Condition                 | 70% |
| Roller Condition                   | 60% |
| Track Canon Condition              | 70% |
| Left Side Undercarriage Condition  | -   |
| Undercarriage Bushings             | 75% |
| Undercarriage Shoes                | 80% |
| Front Idler Condition              | 80% |
| Rear Idler Condition               | 80% |
| Carrier Roller Condition           | N/A |
| Track Links Condition              | 80% |
| Sprocket Condition                 | 70% |

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



# PLANT & EQUIPMENT AUCTIONS

|                         |                                   |
|-------------------------|-----------------------------------|
| Roller Condition        | 60% , one need change             |
| Track Canon Condition   | 70%                               |
| Track Width Measurement | W560 / L240 /Grouser height 45 mm |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

## PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

